



MECHANICAL CLEANSING SERVICES LIMITED

*Tank Cleaning & Degassing × Interceptor Waste Removal × Bund Wall Cleaning × Wash bays & Grease trap
Cleaning effluent Waste Removal × Forecourts & Watercourse Spillage Recovery*

CLEANING, DEGASSING, AND REMOVAL OF FUEL TANKS

September 2010

Case Study: Wellesley Square, Croydon

Our Client required two 5000 Gallon fuel tanks to be removed.

The tanks were within a storage bunker. The bunds were contaminated with waste water and debris.

MCS provided the following services:

- Draining and disposal of residual product
- Uplift of tank bottoms and removal of sludge using vacuum tankers
- Clearance and flushing of pipe work
- Manual cleaning of tanks using Confined Space trained operatives
- Remote mechanical cleaning using high pressure washing
- Testing and issuing of gas free certificates by certified personnel

MCS removed the waste water and cleaned and degassed both tanks. After testing and issuing of gas free certificates, the tanks were then professionally cut out into manageable sections for recycling.





MECHANICAL CLEANSING SERVICES LIMITED

*Tank Cleaning & Degassing × Interceptor Waste Removal × Bund Wall Cleaning × Wash bays & Grease trap
Cleaning effluent Waste Removal × Forecourts & Watercourse Spillage Recovery*



More pictures to add.